

514 112 A
IDEA-2000-64
Copy__of__

1 May 1964

MEMORANDUM FOR : Assistant Director of Special Activities
SUBJECT : 112A Delta I Camera

1. Preliminary report of failure on GT-3892 indicates satisfactory ground check and airborne clearing cycle of camera, however, ground examination after flight shows that film parted after starting into the take up spool.

2. This camera has no film breakage shut off switch and the camera continued to cycle although the film was not being moved.

3. An electrical engineer is enroute to Barksdale to install the above feature which had been previously incorporated in the later 112B Delta II version. Full report will follow as information is received.

[REDACTED]
SSD/OSA

25X1A



25X1A

SSD/OSA [REDACTED] :gp (1 May 1964)


- Cy 1 - AD/OSA
2 - D/TECH/OSA
3 - SSD/OSA
4 - chrono
5 - RB/OSA



SECRET



ELI'D →




← Rear




← FWD



← Toward



← Rear



← FWD

EQUIPMENT BAY

LEFT SIDE FROM
UPPER RIGHT

BULKHEAD 252 ON RIGHT
" 306 ON LEFT

EQUIPMENT BAY

RIGHT SIDE FROM
UPPER LEFT.

BULKHEAD 252 ON LEFT
" 306 ON RIGHT

LEFT SIDE VIEW APPROX.
LEVEL WITH W.L. 100

BULKHEAD 252 ON LEFT
" 306 ON RIGHT
" 319 ON FAR RIGHT



← Forward



Bottom View